## <u>Post-Hurricane Sandy Status Report for Region 2 Superfund Remedial Sites</u> Located in Emergency Declaration Counties

Full, Official Site Name: Welsbach and General Gas Mantle Contamination Site

Site Address or Location, including County: Camden and Gloucester City, Camden County, NJ

Lat/Long for Site (if you can get this information):

Date of Inspection: <u>10/31/2012</u>

Name of Inspector: <u>John Johnson, Construction Representative</u>

Affiliation of Inspector (EPA/Contractor/PRP/etc.): <u>U.S. Army Corps of Engineers</u>

Best phone number to reach inspector: <u>856 742-5630 x311</u>

Do conditions at the site pose an immediate threat to human health or the environment?

\_\_\_\_Yes \_\_\_X\_No

If Yes, please provide a brief description of the conditions and the necessary response actions:

N/A

Briefly describe any equipment damage, operational problems, etc.:

No damage to equipment, Newton Creek overflowed its bank and flooded the Ballfields South project site; however, the excavation areas were not impacted. Sevenson dewatered the site on 10/31 and 11/1, and resumed normal operations on 11/5.